

UTAH 3809 COMPLIANCE INSPECTION REPORT

Contract: U-79710

Field Office: UT-100

Operator(s): Color Country Rock (Windy #3)

Project name: Windy Banded Sandstone Quarry

Location: T41S R18W Sec 13 S1/2

Disturbance: Disturbed area of about 4 acres has not changed, contains 3,500 ft long access road and 50 ft by 300 ft open-cut that is up to 12 ft high. Open-cut in liesegang banded sandstones in the Shinarump Member of the Chinle Formation. Some ATV traffic to the site.

Hazardous Materials on Site: None/The site is stable and fairly clean.

Comments: Inspection with Lynn Kunzler, UDOGM. No activity and no evidence of recent production of sandstone.

Instructions to Operator: Access road needs re-grading on steep slopes.

Recommended Action(s): Contact operator to discuss future operating plans.

Photographs Taken: See Photographs below.



Inspector: Russell Schreiner

Date of Inspection: April 14, 2010

Reviewed by: _____
FM, St.George Field Office

Date: _____



View of the working face in Shinarump sandstone looking north, there has been no recent mining activity.

RECEIVED

MAY 03 2010

Div. of Oil, Gas & Mining



View of the restricted cultural area.